August 25, 2010		6 1450 AM									Page 1
Item ID: I Revision ID:	D3942-1			Accept				S	etup Sta		
	Angle								Sto	р	
Start Date: 8 Required Date: 8 Reference:	3/25/10 3/27/10	Start Qty: 32.0 Req'd Qty: 32.0			Cust Item I Customer:	D:					
Approvals:	Process I	Plan: CL	Date: 12/8	/25 Tooling:	 	ıte:	-	R	lun Sta	rt 	
	QC:	Tian	Date:	SPC (Y/N):		ite:			Sto	р	
Sequence ID/ Work Center ID		Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	R	Levision Nbr									
100				0.00							
Waterjet		Memo		0.00				1B 10	-8-2-	J	
FLOW CNC Waterjet		Dwg Rev Prog Rev								(DE	À



110

QC2- Inspect parts off machine FAI/FAIB

0.00

Memo

0.00

1310-9-57

Quality Control

W/O:			WO	RK ORDER CHANG	GES				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								, , o <u>a</u> g.	
								:	
								i	
Part No	•	PAR #:	Fault Categ	ory:	_ NCR: Yes	No DQ	A:	Date:	
	Res	solution:	Disposition	:	QA: N/C CI	osed:		Date: _	.
NCR:		,	WORK ORDE	R NON-CONFORM	ANCE (NCF	()			
DATE	STEP	Description of NC						Approval Chief Eng	Approval
DAIL	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Date				QC Inspector

NOTE: Date & initial all entries

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

Work Orde August 25, 2010														Page 2
Revision ID:	D3942-1 Angle			A	ccept						Setup	Start Stop		
Start Date: Required Date: Reference:	8/25/10 8/27/10	Start Qty: 32.00 Req'd Qty: 32.00					Cust Item I Customer:	D:						514 0 101 1183 1894
Approvals:		n:			Tooling: SPC (Y/N):			ıte:			Run	Start Stop		
Sequence ID/ Work Center II 120 QC Quality Control)	Operation Description QC8- Inspect parts - seco	ond check		Set Up/ Run Hours 0.00	04/30	Tool ID	Tool #	Plan Code	Accept Qty Gun AIS	Qt		Reject Number	Insp. Stamp
130 Brake NC Brake NC		Memo 1- Bend as p	per dwg D3942		0.00 0.00 SB	(0/08	131			[19		· · · · · · · · · · · · · · · · · · ·		
140		QC5- Inspect part compl	leteness to step o	on W/O	0.00	210	loslal			cant (XII				

0.00

Memo

Quality Control

W/O:			W	ORK ORDER CHANGE	ES				
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								Prod Mgr	

Part No		PAR #:	Fault Cat	egory:	NCR: Yes	No DG	A:	Date: _	
	R	esolution:	Dispositi	on:	QA: N/C CI	osed: _		Date: _	
NCR:			WORK ORI	DER NON-CONFORMA	NCE (NCF	₹)			
DATE	DATE STED Description of NC			Corrective Action Section		Verif	ication	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		Section C	Chief Eng	QC Inspector
					i.				
						·			
	·								
						}			

NOTE: Date & initial all entries

[&]quot;H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

Work Order ID 61450

Page 3

August 25, 2010 11:33:59 AM

Item ID:

D3942-1

Accept

Accept

Qty

Setup Start

Stop



Revision ID:

Item Name:

Angle

Start Date:

8/25/10

Start Qty: 32.00 Req'd Oty: 32.00

Cust Item ID:

Customer:

Tool ID

Required Date: 8/27/10

Reference: Approvals:

Process Plan:

Date: Date:

Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date:

Date:

Tool # Plan

Code

Run

Start



Sequence ID/

Work Center ID

150

Packaging

Packaging

Operation Description

QC:

Identify as per dwg & Stock Location:

Memo

0.00

0.00

QC21- Final Inspection - Work Order Release

OC Quality Control Memo

0.00

0.00

Stop

Reject

Reject Number

Stamp

W/O:			WC	ORK ORDER CHANG	ES					
DATE	STEP	PRO	CEDURE CHA	NGE	В	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			·		į					
										·
Part No	:	PAR #:	Fault Cate	gory:	_ NCR:	Yes N	lo DQ	A:	_ Date: _	
	R	esolution:	Dispositio	n:	_ QA: N	/C Clos	sed:		Date: _	
NCR:		\	WORK ORD	ER NON-CONFORMA	ANCE (NCR)				
DATE	ATE STEP Description of NC		Corrective Action Section B			Sign &		Verification		Approval
- JAIL	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng		Date	Sect	ion C	Chief Eng	QC Inspector
-										
£										
	į									
									Ī	

NOTE: Date & initial all entries

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

Picklist Print

August 25, 2010 11:33:58 AM

Work Order ID: 61450

Parent Item: D3942-1

Parent Item Name: Angle



Start Date: 8/25/10

Required Date: 8/27/10

Start Qty: 32.00

Required Qty: 32.00

Comments:

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Primary Item Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304S18GA		Purchased	No		100	sf	159.0479	0.015	0.505263			
									1	10-8	->7	

304/316 .050 Sheet

Location	Loc Oty	Loc Code	
MAT20	159.0479		
111743	8.86		
112885	28.0179		113888
113062	58.17		
115389	64		- <u></u>
	1		

W/O:	3		V	ORK ORDER CHANG	ES			
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date Qty	Approval Chief Eng /	Approval QC Inspector
			•				Prod Mgr	GO MSPECIO
Part No	.	PAR #:	Fault Ca	tegory:	_ NCR: Yes f	No DQA:	Date: _	
	R	esolution:	Disposit	ion:	_ QA: N/C Clo	sed:	Date: _	· .
NCR:		V	VORK OR	DER NON-CONFORMA	NCE (NCR))		
DATE	STEP	Description of NC		Corrective Action Secti		Verification		Approval
DAIL	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
								!
	:							

NOTE: Date & initial all entries

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

DART AEROSPACE LTD	Work Order:	61450
Description: Angle	Part Number:	D3942-1
Inspection Dwg: D3942 Rev: A		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
3.06	+/-0.030	3,069	4		V BOD	
0.75	+/-0.030	625:	*		ν	
Ø0.129	+0.005/-0.001	131	4		V	
0.75	+/-0.030	675.	ž.		V	
0.25	+/-0.030	363	æ		٧	-
0.25	+/-0.030	, 353	>		V	• • • • • • • • • • • • • • • • • • • •
0.25	+/-0.030	. 365	7		V .	
0.35	+/-0.030	,350	>-		$\sqrt{}$	
	·					·

Measured by:	iB.	Audited by:	Prototype Approval:	N/A
Date:	10-8-37	Date: 10/08/30	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	09.06.22	New Issue	KJ 44	AL



